Facilities Committee Meeting Central Office Room November 7, 2016 / 5:30pm Detailed Agenda

I. OPENING PROCEDURES

- A. Time- Call to Order
- B. Recording of attendance by the Secretary
- II. APPROVAL OF MINUTES OF September 26, 2016

III. PRESENTATIONS / REPORTS

Hopewell Update - Grounds, Landscaping, Open & Completed

- Paving: township and contractors working to finish link to Bowood Street to new building parking lot.
- Trees & Grass: all planted
- HVAC Programming, commissioning balancing: contractors are still working to resolve
- Flooding during rain: recommending adding risers to all drains
- Switchgear Insurance Claim \$135,025.19

Hopewell Allowances - Contract/Budget Status

- Contractor Contract Status
 - General Contractor Contract, \$10,448,500 Remaining, \$75,410.55
 - Plumber Contract, \$835,000 Remaining \$0
 - Mechanical Contract, \$2,630,000 Updated w/ Geothermal CO, \$3,025,241.00
 - Electrical Contract, \$2,013,538 Remaining, \$34,308.57
 - Asbestos Removal Contract, \$86,988 Final, \$81,088
 - · Total Contracts \$16,014,026
 - Emergency Contingency Wells \$395,241
 - Total with changes \$16,409,267

Facilities Committee Meeting November 7, 2016

Hopewell Allowances – Continued

- Mailbox and Riser Recommendation
 - Recommending larger mailboxes at a cost of \$9,326
 - Recommending adding risers to address standing water and draining into storm sewer at a cost of \$6,364.05.

Lower Milford Appraisal Update

- Appraisals are in process and on schedule First occurred October 1, 2016 & second will occur October 8, 2016
- The group interested in the building has expressed interest indicated another option for the purchase of a building on November 4, 2016
- Discussion: feasibility and cost involved in bringing up to code capacity of building feasibility of all day kindergarten.

IV. CURRENT BUSINESS

Hopewell Playground – Allowance/Change Order Recommendation

- Reinstallation cost is \$41,310 plus mulch, raised border, sidewalk, and grading. **Final cost** for reinstallation is anticipated at \$45,000 to \$48,000
 - An exact playground new is \$83,760 plus mulch raised border, sidewalk, and grading. Anticipate cost if purchased new will be \$87,000 to \$90,000.
 - The cost of the existing playground in 2009 was \$63,159. It has a 15 year warranty.
- Reinstallation of existing playground is being recommended to be done by an certified installer (safety reasons)
- Installation potential for December.

Hopewell Playground – PTA discussion / Proposal submitted

 Following Facility Committee discussion, their recommendation to the School Board will be for the entire playground "reinstallation" + new pieces, not to exceed \$70,000. This includes the amount of money that the PTA will contribute.

It

Facilities Committee Meeting November 7, 2016

Batting Cage – Recommendation for Installation at High School – will appear on agenda for Nov 14th Board meeting.

- Installation of a Batting Cage at a cost of \$33,497.10 is recommended.
- Installation from point of order is currently 6 8 weeks, will be able to be used for upcoming sports seasons.

Preston Lane – Recommendation for Plan in Cooperation with Upper Saucon Township

- Upper Infiltration to install subsurface District's cost would be approximately \$100,000. Concern of standing water if above surface and appearance.
- Cost to install underground pipe from circle to 378 would be \$30,000. Above surface may be treated as infiltration swale with uncut grasses or could cause maintenance issues.
- District is looking for direction during 2016. This project would be 2017 or 2018. If easement
 is given to township, it will remain district owned but the township will be responsible to
 maintain.

High School Weight Room

• Some equipment is antiquated. Athletics is looking into options addressing safety, function and use for potential upgrade.

VI. VISITORS' COMMENTS

VII. ADJOURNMENT















CHANGE ORDER and MATERIAL ALLOWANCE LOG Lobar (GC)

Original Contract Amount	\$ 10,448,500.00
Starting Allowance	\$ 172,350.00
Allowance Issued	\$ 96,939.45
Allowance Remaining	\$ 75,410.55
Total Change Order	\$ -
Updated Contract Amount	\$ 10,448,500.00

COR#	Description		Amount	СО	Change Order	AAGC	All	owance Adj. Amount
1	Delete exterior courtyard benches per proposed Credit Change Order GC-001.	\$	Requested (22,593.29)		Amount	1	\$	(22,593.29)
2	Addiutional cost for sewer manhole drop at existing manhole per proposed Change Order GC-002.	\$	5,638.33			2	\$	5,638.33
3	Additional cost for wireless gym scoreboard controller per proposed Change Order GC-003.	\$	1,004.85			3	\$	1,004.85
	Additional cost for removal and replacement of unsuitable soils with structural stone inside building pad per	Ė	,					,
4	proposed Change Order GC-004	\$	11,499.95			4	\$	11,499.95
5	Apply masonry sealer to interior Type B masonry	\$	2,192.29			5	\$	2,192.29
6	Sanitary piping revisions at grease trap (Void, refer to COR #12)							
7	Soil exchange at east end of building pad (Void, contractor means and methods)	\$	4,466.00					
8	Remove 33 lin. ft. of wall padding from the gym	\$	(2,900.00)			5	\$	(2,900.00)
9	Remove tree at southwest corner of the building	\$	1,339.80			5	\$	1,339.80
10	Add tackboards to the exterior wall of classrooms	\$	4,923.77			5	\$	4,923.77
11	Provide concrete slab in mechanical area in lieu of stone	\$	4,914.58			5	\$	4,914.58
12	Sanitary piping revisions at grease trap	\$	1,427.78			5	\$	1,427.78
13	Provide access panels to attic space (Void, size will be revised. Refer to COR #16)							
14	Provide tackboards per ASI GC-015 for sound attenuation (Void, refer to COR #15)							
15	Provide acoustical wall panels for sound attenuation (Void, cost proposal was only \$295.08)							
16	Provide (4) 24x24 access panels into attic space	\$	2,633.79			6	\$	2,633.79
17	Added steel angle support for roof trusses in the cafeteria	\$	1,224.80			7	\$	1,224.80
18	Value engineering items for terrazzo flooring (not all items accepted)	\$	(15,300.00)			8	\$	(13,600.00)
19	Provide plate steel for HVAC curb support	\$	3,294.23			10	\$	3,294.23
20 a	Additional storage room adjacent to classroom (Void, work will not be performed)	\$	7,879.05					
21	Gymnasium duct support (Void, refer to COR #23)	\$	16,117.59					
22	Provide modified stone in lieu of on-site material for utility trench backfill - Phase 1	\$	28,638.23			9	\$	28,638.23

Page 1 of 2



COR#	Description	Amount Requested	СО	Change Order Amount	AAGC	Allowance Adj. Amount
23	Provide 10 glulam support members for ductwork installation in the gymnasium	\$ 9,354.95			11	\$ 9,354.95
24	Provide 10" wet taps in lieu of 6" due to existing water main size	\$ 5,085.87			12	\$ 5,085.87
25	Delete images from AP-2 wall panels	\$ (2,251.00)			13	\$ (2,251.00)
26	Increase chain link fence height at solar to 6 ft. (Void, must be 7 ft. per code)					
27	Adjust grades in the courtyard	\$ 5,193.59			15	\$ 5,193.59
28	Provide sod in the courtyard	\$ 18,031.48			16	\$ 18,031.48
29	Increase chain link fence height at solar to 7 ft.	\$ 6,140.75			14	\$ 6,140.75
30	Add window in media center	\$ 1,361.95			17	\$ 1,361.95
31	Added metal work at dormers	\$ 2,039.85			18	\$ 2,039.85
32	Increase size of dedication plaque (Rejected)	\$ 630.80				
33	Mechanical room exit devices	\$ 2,628.14			19	\$ 2,628.14
34	Terrazzo overtime	\$ 4,076.59				\$ 4,076.59
35	Door closer hold open arms	\$ 3,873.17			20	\$ 3,873.17
36	Install GWB and paint at theatrical lighting pocket	\$ 2,244.15				\$ 2,244.15
37	Install temporary stone walkway for teacher access to Area B	\$ 1,067.08				\$ 1,067.08
38	Provide stainless steel jamb at dishwasher pass-thru opening	\$ 909.23				\$ 909.23
39	Field paint storefront blue color	\$ 1,099.75				\$ 1,099.75
40	Install silt soxx at 12 inlets to open infiltration bed	\$ 1,444.79				\$ 1,444.79
41	Install playground equipment	\$ 44,660.00				
42	Provide metal trim edges around classroom white boards (VOID, not to be performed)	\$ 3,265.26				
43	Remove and reconstruct peninsula at entrance to bus lot	\$ 6,197.60				\$ 5,000.00



CHANGE ORDER and MATERIAL ALLOWANCE LOG DeWalt Plumbing (PC)

Original Contract Amount	\$ 835,000.00
Starting Allowance	\$ 40,125.00
Allowance Issued	\$ 40,125.00
Allowance Remaining	\$ -
Total Change Order	\$ -
Updated Contract Amount	\$ 835,000.00

COR #	Description		Amount	СО	Change Order	AAPC	Allow	ance Adj.
COR #	Description	F	Requested	CO	Amount	AAPC	Α	mount
1	Additiojnal cost to install radon vent piping per change order PC-001.	\$	9,462.05			1	\$	9,462.05
2	Revise sanitary grease piping to stainless steel	\$	9,708.00			2	\$	9,708.00
3	Additional classroom closet in Area C (Void, room will not be added)	\$	2,213.00					
4	Provide 31 mixing valves for type "S" sinks	\$	12,443.76			3	\$	12,443.76
5	Gymnasium sprinkler piping - additional 4" main	\$	6,487.00			4	\$	6,487.00
6	Concealed sprinkler head covers at media center wood	\$	649.73				\$	649.73
7	Replace 4" and 6" bird screens	\$	186.60				\$	186.60
8	Complete miscellaneous work in the kitchen	\$	1,552.63				\$	1,187.86



CHANGE ORDER and MATERIAL ALLOWANCE LOG JBM Mechanical (MC)

Original Contract Amount	\$ 2,630,000.00
Starting Allowance	\$ 121,000.00
Allowance Issued	\$ 65,957.56
Allowance Remaining	\$ 55,042.44
Total Change Order	\$ 395,241.00
Updated Contract Amount	\$ 3,025,241.00


COR #	Description		Amount	СО	Change Order	AAMC	All	owance Adj.
		Requested		Amount			Amount	
1	Geothermal well field revisions	\$	395,241.00	1	\$ 395,241.00			
2	Provide armaflex duct liner for acoustical treatment	\$	4,806.03			1	\$	4,806.03
3	Provide additional ductwork for energy recovery exhaust	\$	13,858.70			4	\$	13,858.70
4	Additional storage room in Area C classroom (VOID, work not to be performed)	\$	470.96					
5	Provide modified stone backfill for geothermal trenches	\$	45,143.61			2	\$	45,143.61
6	Reduction of support needed in gymnasium for spiral ductwork	\$	(2,000.00)			3	\$	(2,000.00)
7	Insulation on ductwork in Area A located above hard ceiling	\$	1,542.75			6	\$	1,542.75
8	Adjust rough-ins and equipment pad for Area B ERU (Rejected)	\$	6,001.37					
9	Provide additional return air grille in the cafeteria	\$	338.83			5	\$	338.83
10	Provide sheet metal shroud over switchgear	\$	2,267.64			7	\$	2,267.64



CHANGE ORDER and MATERIAL ALLOWANCE LOG Albarell Electric (EC)

Original Contract Amount	\$ 2,013,538.00
Starting Allowance	\$ 102,979.00
Allowance Issued	\$ 68,670.43
Allowance Remaining	\$ 34,308.57
Total Change Order	\$ -
Updated Contract Amount	\$ 2,013,538.00

COR#	Description	Amount Requested	СО	Change Order Amount	AAEC	Allowance Adj. Amount
4	Additionl charge to change globe light fixture size in Lobby per proposed Change Order EC 001. (V	\$ 2,311.00				
2	Additional charge to add fire alarm devices per proposed change Order EC-002. (VOID)	\$ 4,974.00				
3	Delete floor box in serving line (VOID - receptacle will be re-located to wall)	\$ (439.00)				
4	Provide data drops to phone designations	\$ 8,551.00			1	\$ 8,551.00
5	Provide conduit in gymnasium in lieu of MC cable	\$ 5,675.00			2	\$ 5,675.00
6	Additional classroom storage room in Area C (VOID, work not to be performed)	\$ 824.00				
7	Provide modified stone for service trench backfill	\$ 18,066.00			3	\$ 18,066.00
8	Furnish duct detectors for HVAC units	\$ 20,815.00			4	\$ 20,815.00
9	Provide circuit for instantaneous water heater in music room	\$ 1,431.00			5	\$ 1,431.00
10	Labor costs for switchgear replacement (VOID, to be paid by insurance)	\$ <u>26,715.00</u>				
11	Premium labor time; weekend work	\$ 8,752.62				\$ 8,752.62
12	Costs for drying of switchgear following water infiltration (VOID, to be paid by insurance)	\$ 1,811.46				
13	Miscellaneous additional work in the kitchen	\$ 2,339.52			6	\$ 2,339.52
14	Add speaker in nurse suite	\$ 1,176.00			7	\$ 1,176.00
15	Add receptacles for copiers in Area B	\$ 1,131.00				\$ 1,131.00
16	Add data jacks for copiers in Area B	\$ 733.29				\$ 733.29
17	Fire watch for switchgear (VOID, to be paid by insurance)	\$ 2,406.73				





GENERAL ADD-ONS

Rate			Amount
1.50%	Bond		\$94.05
		Subtotal Add-ons:	\$94.05

Only the work specifically detailed and priced above is included in this proposal. Any other work required is not included. This proposal is valid for fifteen (15) calendar days. We can proceed with this additional work as soon as written authorization as provided by the Contract documents is received. This additional work will require a 0 day(s) time extension.

Any costs incurred as a result of a time extension will be compiled and submitted for reimbursement. It is expressly understood between the
















1?Jroject:Hopewell

ITCJPS rep: **Tony Casciano Boyce Associates** 800-441-9400

Kid Builders:

Post Mmal: Galvanized Post Color: Forest Green Accent Color:Forest Green

Panel Color: Tan Slide Color: Tan

Roof Color: Forest Green

Hex Wedge:None Hex 1Rib: None **Mounting: Buried**

Drawn by: Galbe lindsey

Date: 17119/C6

DWG Name: QU031953

Scale:118"=1' Approved by:

LTCJPS- Farmington One Iron Mountain Drive Farmington, Missouri 63640

Voice: 1-800-325-8828 Fax:573-7S 319

GENERAL NOTES

- 1. The Americans wl\h Disabili\les Ac\ (ADA) may require \ha\ ycu make ycur pork and/or plo)\'\text{Qround} acceuiblt when viewed in 1\t entirely. Pleaat conaul\)\(\text{IOUr}\) 11901 counael to de\ermine if the ADA applies \o you.

 2. f"or pla)\'\text{Qround}\) oqulpmen\ to be considered acceuible, acceuible aurfacing muo\ be utilized in applicable oreoo.

 J. Although a particular pla)\'\text{Qround}\) deaign may not meet tht

propoatd Accua Boord Regulation In revorda to tht appropriate number of ground level eventa, the actual playground may be In compliance when conoldering e-la\lng

- play componenta.

 4. All deck htlghtlore measured from top of ground cover f'all absorbing ground cover 11 required under ond around all play equipment.
- 6. The minimum recommended fall zone around tho entire ploye\ructure 11thawn. Thit zane la to be fret of all

		===-h	Area 724 sq. feet Perimeter 107 feet	tripping or colllalan hazi materiol etc.). 7. This playetructure(a) me requirements of ASTM fr
maygroundllLayout Compliance: D'This playground design meets the final Access Boaro Regulations. BCJPSC Handbook foli' lPublic Playground Safety		r32'-8	8 ''1	tripping or colllalan hazi materlol etc.). 7. This playetructure(a) me requirements of ASTM frequipment moy be appr is required. 8. All paot length* are idelengths.i.e. 8e represence in the properties of the players of the player
BAS'lrM F1487 - IPlaygrowd Equipment for IPublic IUse.				
	1			

zards (I.e. roota. roelct, border

neeta the performance and tafety for children!1-12 years old. Not all propriate for oil chndren. Supervision

entified by ted ohowing the poot enta a 96 Inch poet. Ire panel locationt ore marked eight of each panel may be found est deck from the higheo\ deck deck encloaure panel mounta.

MILLER FLOORING COMPANY, INC. SPORTS CONSTRUCTION DIVISION 827 LINCOLN AVENUE, UNIT 15 WEST CHESTER, PA 19380

KPN PROPOSAL

TO: TODD BERGY- SOUTHERN LEHIGH S.D.	FROM: BILL MILLER
JOB: INSTALL BATTING CAGE AND REMOVAL TURF	DATE: NOVEMBER 2, 2016

Todd: I have prepared a proposal for the supply and install of a batting cage and turf. We propose to supply all materials, labor and equipment necessary to complete work as further specified.

KPN Pricing: The pricing is based on the PA State approved AEPA national cooperative pricing contract. The contract is administered by KPN (Keystone Purchasing Network) by Jeff Kimball. Because the contract was bid and awarded on a national level the bidding process does not need to be duplicated.

KPN Contact: Jeff Kimball (570) 523-1155 x2130 Contract #: KPN- A-201202-01B

Grand Slam Batting Cage (14'W x 25'H x 70'L): This is the premium option which costs more but is fully automatic. This model uses frame work on the bottom of the cage where option 1 does not. When the cage is lowered from the ceiling the bottom rail lowers to the floor with the netting attached. As the cage raises the bottom rail gathers the netting and self- stores. We will supply the electric materials and labor required with a licensed electrician.

Number	Scope	Unit	Price	Total
IFB#012-B	Batting Cage Turf	16,485	1.26	\$20,771.10
	Electric Supplied	2,110	1.26	\$ 2,658.60
				\$23,429.70

<u>Curtain Adjustment:</u> Cut the existing curtain back to create enough clearance to add the batting cage. This work requires lowering the curtain cutting the vinyl/mesh, hem the cut edge to the new size and reinstallation.

Number	Scope	Unit	Price	Total
IFB#012-B	Curtain Adjustment	4,500	1.26	\$5,670.00

Batting Cage Turf: Supply and deliver one (1) piece 12' x 70' of AT740 Turf w 3mm pad. Owner is to off load material upon arrival

Number	Scope	Unit	Price	Total
IFB#012-B	Turf 12' x 70'	3,490	1.26	\$4,397.40

Clarifications: Three (3) to four (4) weeks lead time. The owner is responsible for; use of school dumpster for debris, electric supply to equipment, use of rest rooms and 24/7 access.

Exclusions: Bonds, permits, prevailing wage rates and taxes.

Terms: Net 30- 1.5% per month late fees- NO retainage held. Service charges added for credit card payments.

Acceptance: The above terms, pricing, specifications and conditions are satisfactory and hereby approved. Payments will be made as outlined above.

Authorized Signature:		_,		
O	Southern Lehigh S.D.	Date		
Authorized Signature:	Wm. H. Miller			
	Bill Miller	Date		
To process this order please sign and fax to (610) 626-3000 or email to $\underline{\text{cmartin@millerflooring.com}}.$				

TEL: (610) 626-1000 FAX: (610) 626-3000





